DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-006255

Address: 333 Burma Road **Date Inspected:** 20-Apr-2009

City: Oakland, CA 94607

OSM Arrival Time: 645 **Project Name:** SAS Superstructure **OSM Departure Time:** 1845 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: Zhao Chen Sun **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component: OBG** components

Summary of Items Observed:

On this date CALTRANS OSM Quality Assurance (QA) Inspector, Dilip Chakrabarti was present during the times noted above for observations relative to the work being performed.

Bay# 6-OBG Assembly

This QA Inspector randomly observed the following work in progress:

Magnetic Particle Testing:

For Green Tag:

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated a TL-6028 MT report on this date. The member and the weld designations are as follows:

Sl # Section # Weld # Green Tag # Location

- 1. BP 202-209 002,003,004 006484 8 A
- 2. EP 141-001 001,002 006486 11 DW
- 3. EP 157-001 019,020 006488 11 BE
- 4. EP 138-001 019.020 006487 11BW
- 5. EP 140-001 007,008 006485 11DW
- 6. EP 170-001 002,004 006990 11 AE
- 7. EP 156-001 005,007 006986 11 BE

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

8. SP 663-001 006,008,010 006984 11 AW

Bay# 6-Tower Assembly

This QA Inspector randomly observed the following work in progress:

SMAW Process:

Root pass welding of weld joints# B/B-20,22,24 located on PCMK ESD1 DPSA4-4. Welder is identified as 066261. ZPMC QC is identified as Zhang Bao Bo. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-3313-TC-P5.

Root pass welding of weld joints# B/B-21,23,25 located on PCMK ESD1 DPSA4-4. Welder is identified as 066416. ZPMC QC is identified as Zhang Bao Bo. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-3313-TC-P5.

Bay # 7-OBG Assembly:

This QA Inspector randomly observed the following work in progress:

FCAW Process:

Welding of weld joints# 1&2 located on PCMK DP 203-009. Welder is identified as 054459. ZPMC QC is identified as Zhong Chong Biao. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-4132.

Welding of weld joints# 5&6 located on PCMK DP 203-009. Welder is identified as 205774. ZPMC QC is identified as Zhong Chong Biao. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-4132.

Welding of weld joints# 3&4 located on PCMK DP 203-009. Welder is identified as 062447. ZPMC QC is identified as Zhong Chong Biao. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-4132.

Unless otherwise noted, all work observed on this date appeared to be generally comply with applicable contract document

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Chakrabarti,Dilip Kumar	Quality Assurance Inspector
Reviewed By:	Clifford,William	QA Reviewer